HAER WASH 32-CHEN, Y

HISTORIC AMERICAN ENGINEERING RECORD INDEX TO PHOTOGRAPHS

Company Ditch

Turnbull National Wildlife Refuge, near the intersection of Lance Hill and Mullinex roads.

Vicinity of Cheney

Spokane County,

Washington

3		
Harvey S. Rice, Pho	otographer Oct	ober 1995
WA-138-1	THE COMPANY DITCH NEAR ITS BEGINNING AT THE END. LOOKING NORTHEAST.	HE WEST
WA-138-2	THE COMPANY DITCH IN THE MEADOW WEST OF MUROAD. LOOKING WEST.	ULLINEX
WA-138-3	THE COMPANY DITCH IN THE MEADOW WEST OF MUROAD. LOOKING SOUTHWEST.	ULLINEX
WA-138-4	THE COMPANY DITCH HEADING TOWARD THE HELM LOOKING NORTHWEST.	1 PLACE.
WA-138-5	SCREW-VALVE HEADGATES, NEAR MULLINEX ROAD. I SOUTHEAST.	LOOKING
WA-138-6	COMPANY DITCH, LOOKING FROM HEADGATES. I SOUTHEAST.	LOOKING
WA-138-7	CULVERT UNDER MULLINEX ROAD. LOOKING EAST	•